
Remove the top cover and base of the pedestal.
(Not fastened to pedestal for quick disassembly)






 Remove the required rubber plugs and attach screws and washers (hardware by others) for mounting the charger.




• Attach an appropriate strain relief and secure it from inside the pedestal (Tool access through top).




 Hook the charger to the pedestal using the top mounting screw and secure it in place using the bottom screw.






• Use a cable of atleast 5' length and connect one end of the cable to the charger terminals and feed the other end through the strain relief into the pedestal.



- Attach the pedestal mounting plate on the ground with provided anchor bolts.
- Pull the power line through the bottom of the pedestal and connect it to the cables coming from the ground.



- Slide the Pedestal over the base and fasten using 4 screws provided.
- Attach the top cover using the 8 screws provided





 Attach the charger cover using the Charger hardware.

